

From: [Sanchez, Carlos](#)
To: [Meyer, John](#); [Miller, Garyg](#)
Subject: RE: My revisions to write up
Date: Monday, March 07, 2016 5:09:51 PM

John,
That it is accurate. CAS

From: Meyer, John
Sent: Monday, March 07, 2016 4:24 PM
To: Sanchez, Carlos; Miller, Garyg
Subject: My revisions to write up

Let me know if this is accurate. thanks

San Jacinto March 7, 2016

On March 4, 2016, EPA was notified by the Potentially Responsible Parties that a visual inspection of the cap at the San Jacinto River Waste Pits Superfund Site revealed additional areas where rock was displaced from the cover. This unscheduled inspection took advantage of the recent low tides, which exposed a majority of the eastern cell of the waste pits for visual inspection. Five small (approximately 1 foot by 3 foot at the largest) areas were observed with exposed geotextile. No waste material was exposed.

On March 7, 2016, the EPA directed the PRPs to place additional rock over these areas and approved a plan to conduct this work under EPA oversight. The PRPs are scheduled to conduct this work the week of March 7, 2016.

A full cap inspection will be conducted by EPA's Dive Team in early April 2016. Following the inspection, sample devices will be placed by the divers to measure if any wastes are moving through the site cover. A community meeting is scheduled for late May 2016, to update the community on site activities and present the findings from the Corps of Engineers on potential final remedies for the site.

John C Meyer
Remedial Branch Chief
Superfund Division
214.665.6742



9769126